



Objectives

- Internalize quality, cost, rate and flexibility as mfg attributes.
- **Apply physics** to understand the factors that influence the **quality, cost, rate** and **flexibility** of the **IM process**.
- Apply an understanding of variation to the factors that influence the quality, cost, rate and flexibility of processes and systems.
- Understand the impact of manufacturing constraints on product design and process planning.


Injection Molding Process Window



Product Development Cycle



Simulated vs. Actual Mold Flow



Simulation: Dotted Line

Actual: Solid Line

2.008

Injection Molding II


Objectives

- Internalize quality, cost, rate and flexibility as mfg attributes.
- Apply physics to understand the factors that influence the quality, cost, rate and flexibility of processes.
- Apply an understanding of variation to the factors that influence the quality, cost, rate and flexibility of processes and systems.
- Understand the impact of **manufacturing constraints on product design** and process planning.


Design for Manufacturing

- Part Design
 - Moldable
 - Shrinkage
 - Reinforcements
 - Removable
- Mold Design
 - Mold structure
 - Melt delivery
 - Balancing
- Defects

Non-isothermal Flow



Non-Isothermal Flow



$$\text{Flow rate: } 1/t \sim V/L$$

$$\text{Heat transfer rate: } 1/t \sim a/(T/2)^2$$

$$\frac{\text{Flow rate}}{\text{Heat xfer rate}} \sim \frac{V \cdot T^2}{4\alpha \cdot L} = \frac{1}{4} \frac{VT}{\alpha} \cdot \frac{T}{L}$$

Small value
=> Short shot

For injection molding

$$\frac{\text{Flow rate}}{\text{Heat xfer rate}} \sim \frac{1}{4} \frac{10\text{cm/s} \times 0.1\text{cm}}{10^{-3}\text{cm}^2/\text{s}} \cdot \frac{0.1\text{cm}}{10\text{cm}} = 2.5$$

For Die casting of aluminum

$$\frac{\text{Flow rate}}{\text{Heat xfer rate}} \sim \frac{1}{4} \frac{10\text{cm/s} \times 0.1\text{cm}}{0.3\text{cm}^2/\text{s}} \cdot \frac{0.1\text{cm}}{10\text{cm}} \cong 10^{-2}$$


* Very small, therefore it requires thick runners

Flow Path Ratio

-Flow path ratio is the ratio between L (the distance between the gate and the farthest point in the molding dimension) and T (the thickness of the part) .


-When molding large or thin parts, the flow path ratio is calculated to determine if molten plastics can fill the mold cavity.

Rule of thumb




Polyethylene (PE)	$L/T = 280-100$
Polypropylene (PP)	$L/T = 280-150$
Polyvinyl chloride (PVC)	$L/T = 280-70$
Polystyrene (PS)	$L/T = 300-220$
Polycarbonate (PC)	$L/T = 160-90$
Acrylonitrile butadienstyrene (ABS)	$L/T = 280-120$
Polyamide (PA)	$L/T = 320-200$

Specific Volume of Crystalline Thermoplastics



Temperature

Shrinkage



$$\Delta L = \alpha L$$

$$\Delta T = \alpha T$$


α : shrinkage rate

Resin	Shrinkage (%)
Polyethylene (PE)	1.5-6.0
Polypropylene (PP)	1.0-3.0
Polyvinyl chloride (PVC)	0.1-0.5
Polystyrene (PS)	0.2-0.6
Polycarbonate (PC)	0.5-0.8
Acrylonitrile butadienstyrene	0.3-0.8
Polyamide (PA)	0.6-2.0

Heat Transfer

Note; $\alpha_{\text{Tool}} \geq \alpha_{\text{polymer}}$

1-dimensional heat conduction equation:



$$\frac{\partial}{\partial t} (\rho \cdot c_p \cdot T) \Delta x \Delta y = - \frac{\partial q_x}{\partial x} \Delta x \Delta y$$

Fourier's law

$$q_x = -k \frac{\partial T}{\partial x}$$

$$\rho \cdot c_p \frac{\partial T}{\partial t} = k \frac{\partial^2 T}{\partial x^2} \quad \text{or} \quad \frac{\partial T}{\partial t} = \alpha \frac{\partial^2 T}{\partial x^2}$$

Boundary conditions:

1st kind

$$T(x = x') = \text{constant}$$

2nd kind

$$-k \frac{\partial T}{\partial x}(x = x') = \text{constant}$$

3rd kind

$$-k \frac{\partial T}{\partial x}(x = x') = \bar{h}(T - T_{\infty})$$

The boundary condition of 1st kind applies to injection molding since the tool is often maintained at a constant temperature

Injection Cycle Time


- \$\$\$
- Typical Cycle of Injection Molding
 - Mold Close 1-2 sec
 - Injection 2-5 sec
 - Pack and Hold 8-10 sec
 - Part Cool 10-20 sec
 - Screw return 2-5 sec
 - Mold open 1 sec
 - Ejection 1 sec

Reinforcement


- Thickness increase
- Stiffer grade material
 - PP (unfilled), 4,400 psi tensile strength
 - PP (20% glass filled), 7,700 psi
- Add secondary features, ribs, bosses

Injection Molded Part Design

- Base feature + secondary feature (ribs, bosses, holes, etc.)
- Nominal wall : Keep part thickness as **thin and uniform** as possible.
 - Shorten the cycle time, improve dimensional stability, and eliminate surface defects.
 - For greater stiffness, reduce the spacing between ribs, or add more ribs.
- Nominal wall thickness should be within $+\text{-} 10\%$




Ribs and Bosses




Draft Angle and Parting Line


- For removing parts from the mold
- 1-2°, material, dimension, texture dependent
- Cavity side smaller, core side larger.
- Crystalline material has more shrinkage.
- Amorphous material has smaller shrinkage.



Mold Structure





Mold Structure - Cavity and Core




Mold Structure: Parting Line

A dividing line between a cavity plate and a core plate of a mold.

- Make a parting line on a flat or simple-curved surface so that flash cannot be generated.
- Venting gas or air.




Two Plate Mold





One parting line

Three Plate Mold









Two parting lines

Mold Structure: Undercut, Slide Core



Mold Temperature Control: Even Cooling





Melt Delivery

Sprue

A sprue is a channel through which to transfer molten plastics injected from the injector nozzle into the mold.

Runner



A runner is a channel that guides molten plastics into the cavity of a mold.

Gate


A gate is an entrance through which molten plastics enters the cavity.

Gate

- Delivers the flow of molten plastics.
- Quickly cools and solidifies to avoid backflow after molten plastics has filled up in the cavity.
- Easy cutting from a runner
- Location is important to balance flow and orientation and to avoid defects.




Fan gate, Film gate, Direct gate



Gate Positioning

- Set a gate position where molten plastics finish filling up in each cavity simultaneously. Same as multiple points gate.
- Set a gate position to the thickest area of a part. This can avoid sink marks due to molding (part) shrinkage .
- Set a gate position to an unexposed area of part or where finishing process can be easily done.
- Consider weldline, molecular orientation.

Runner Cross Section




Runner cross section that minimizes liquid resistance and temperature reduction when molten plastics flows into the cavity.


- Too big
 - Longer cooling time, more material, cost
- Too small
 - short shot, sink mark, bad quality
- Too long
 - pressure drop, waste, cooling

Hot runner, runnerless mold


Runner Balancing



Balanced




Not balanced




Cavity
Sprue Bush

Example of Molding
Four Parts



Sprue Bush




Cavity

Sprue Bush

Runner
Runner

Cavity
Sprue Bush
Cavity
Runner

Cavity
Runner



Sprue Bush


Example of Molding
Eight Parts

Defects

Molding defects are caused by related and complicated reasons as follows:

- Flaws in product and mold design
- Inappropriate molding conditions
- Malfunctions of molding machine
- Improper selection of molding material

Short Shot



This is the phenomenon where molten plastics does not fill the mold cavity completely. and the portion of parts becomes incomplete shape.

Cause

The shot volume or injection pressure is not sufficient.

Injection speed is so slow that the molten plastics becomes solid before it flows to the end of the mold.


Solution

- Apply higher injection pressure.
- Install air vent or degassing device.
- Change the shape of the mold or gate position for better flow of the plastics.

Short Shots



Flashes



Flashes develop at the mold parting line or ejector pin installation point. It is a phenomenon where molten polymer smears out and sticks to the gap.

Cause


Poor quality of the mold.

Injection pressure is too high, or clamping force is too weak.

Solution

- Slow down the injection speed.
- Apply well-balanced pressure to the mold to get consistent clamping force, or increase the clamping force.
- Enhance the surface quality of the parting lines, ejector pins and holes.


Sink marks



Collapsed surface

Solution: Equal cooling from the surface

Weldline



This is a phenomenon where a thin line is created when different flows of molten plastics in a mold cavity meet and remain undissolved. It is a boundary between flows caused by incomplete dissolution of molten plastics. It often develops around the far edge of the gate.


Cause

Incomplete dissolution of the molten plastics.

Solution

- Increase injection speed and raise the mold temperature.
- Change the gate position and the flow of molten plastics to prevent development of weldline.


Simulated vs. Actual Mold Flow



Simulation: Dotted Line

Actual: Solid Line

Warpage



This deformation appears when the part is removed from the mold and pressure is released.

Cause

Uneven shrinkage due to the mold temperature difference (surface temperature difference at cavity and core), and the thickness difference in the part. Injection pressure was too low and insufficient packing.



Solution

- Take a longer cooling time and lower the ejection speed.
- Adjust the ejector pin position or enlarge the draft angle.
- Examine the part thickness or dimension.
- Balance cooling lines.
- Increase packing pressure.


Mold Temperature Control

- Hot mold for less residual stresses (orientation)
 - Low thermal inertia
- Even mold cooling with water, oil

Gate Location and Warping




Before shrinkage




After shrinkage


Shrinkage
Direction of flow – 0.020 in/in
Perpendicular to flow – 0.012




Center gate: radial flow – severe distortion



Edge gate: warp free, air entrapment




Diagonal gate: radial flow – twisting



End gates: linear flow – minimum warping

Strength issues



The molecules align in the major direction of flow, and hence there is greater strength.





Image Credits

Slide 8:

© John Wiley & Sons, Inc. All rights reserved. This content is excluded from our Creative Commons license. For more information, see <https://ocw.mit.edu/help/faq-fair-use>.

Slide 17:

© Source unknown. All rights reserved. This content is excluded from our Creative Commons license. For more information, see <https://ocw.mit.edu/help/faq-fair-use>.

Slides 18-26:

© moldviet.net. All rights reserved. This content is excluded from our Creative Commons license. For more information, see <https://ocw.mit.edu/help/faq-fair-use>.

MIT OpenCourseWare
<https://ocw.mit.edu>

2.008 Design and Manufacturing II
Spring 2025

For information about citing these materials or our Terms of Use, visit: <https://ocw.mit.edu/terms>.