


Variation and Quality

Statistical Process Control

1



SPC



Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing

2

2.008 Topic Coverage

Variations

Statistical Representation

Process Capability

Process Control

Accuracy vs Precision

Quality Loss

Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing

3

Statistical Distributions

Probability

$$P\{a \leq x \leq b\} = \int_a^b f(x) dx$$


$$P\{-\infty \leq x \leq \infty\} = \int_{-\infty}^{\infty} f(x) dx = 1 \text{ for all } \bar{x}, s$$

Normalized

$$z = \frac{x - \bar{x}}{s} \quad \text{("number of std devs")}$$

$$P\{z_1 \leq x \leq z_2\} = \int_{z_1}^{z_2} \frac{1}{\sqrt{2\pi}} e^{(-\frac{z^2}{2})}$$

$$f(x) = \frac{1}{2\pi s} e^{\left(-\frac{(x - \bar{x})^2}{2s^2}\right)}$$



Variation and Quality


Defining, Measuring, and Controlling Quality in Manufacturing

Process Capability!

Is the **process capable** of meeting the **design requirements**?

$$C_p = \frac{USL - LSL}{6\sigma_{process}}$$

	Recommended process capability for two-sided specifications	Defects (parts out of spec) per million operations
Existing (stable) process	1.33	63
New process	1.50	8
Existing process, safety-critical	1.50	8
New process, safety-critical	1.67	1
Six-sigma quality	2.00	0.002



Variation and Quality

Statistical Process Control

Yield


Yield = % of acceptable parts

*Total Yield = yield_{step1} * yield_{step2} * yield_{step3} ...*

assuming each step is **independent**

Total Yield \propto Cost

- processes with more stages will have lower yield
- total yield is highly sensitive to one low yield operation





Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing

6

Where do variations come from?



Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing

Where do variations come from?

Systematic / Assignable / Special Cause

detect, chase down, and eliminate or reduce

(you know or can figure out what is happening)

- tool is wearing out
- operator used the wrong depth of cut
- typically a “single direction” shift

Random / Un-assignable / Common Cause

understand, minimize, and coordinate
(with designers, etc.)

make sure these variations are tolerated


(there's always some amount of randomness)

- there's some natural variation due to vibrations, nonlinearities, etc.
- i.e. a truck passed by and caused extra vibration or there was a solar flare
- “positive and negative” shifts

Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing

Where do variations come from?



Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing

9

General Process Control Scheme

Process


Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing

10

General Process Control Scheme

1. Detect disturbances (special causes)
2. Take corrective action




Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing


Process Control

In Control is different from being Capable

- a process is “in control” if it is producing **similar parts in a predictable way over time**
- this is in comparison to a **qualifying run** that provides a benchmark for production
- you need to be able to predict production to properly meet the demand of the customers



out of control (special causes present)



in control (special causes eliminated)

Variation and Quality


Defining, Measuring, and Controlling Quality in Manufacturing

12

Process Control

Ideally a process would be both **in control** (stable over time) and **capable** (able to achieve the design specifications).

$$C_p = \frac{USL - LSL}{6\sigma_{process}}$$



Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing

13

Process Control




So how do we determine if a process is **in control** (stable over time)?

We need to start **charting** the process.

Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing

Run Chart vs Control Chart



Variation and Quality


Defining, Measuring, and Controlling Quality in Manufacturing

15

Control Charts (“Shewhart Charts”)

Properly used, control charts can:

- Be used by operators for ongoing control of a process
- Help the process perform consistently, predictably for higher quality, lower cost and higher effective capacity
- Provide a common language for discussing process performance
- Distinguish special from common causes of variation; as a guide to local or management action



Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing

16

Control Limits

Points outside the limits will signal that something is wrong- an assignable cause.

We want limits set so that assignable causes are highlighted, but few random causes are highlighted accidentally.

As n increases, the UCL and LCL move closer to the center line, making the control chart more sensitive to shifts in the mean.

UCL: upper control limit

LCL: lower control limit

σ_{sg} : standard deviation of the sample


$\sigma_{process}$: standard deviation of the process

$$UCL = \bar{x} + 3\sigma_{sg} = \bar{x} + \frac{\sigma_{process}}{\sqrt{n}}$$

$$LCL = \bar{x} - 3\sigma_{sg} = \bar{x} - \frac{\sigma_{process}}{\sqrt{n}}$$

$$\sigma_{sg} \neq \sigma_{process}$$

$$\sigma_{sg} = \frac{\sigma_{process}}{\sqrt{n}}$$







Control Charts and Quality Loss

Variation & Quality

Western Electric Rules

The Western Electric Rules are chosen because each of these conditions is improbable:

⚠ we are looking at sample mean charts, but range charts can also be used



Variation and Quality

Defining, Measuring, and Controlling Quality in Manufacturing

18

Process Control

What happens if your process is characterized by a **non-normal distribution**?


We need to rely on the **Central Limit Theorem**

Control Charts and Quality Loss

Variation & Quality

Central Limit Theorem

a critical aspect of the sampling process is that **it shapes the data into a normal distribution**
you can start to see the effects even after a sample size of only 2
the bigger the sample size (n), the tighter and more normal the distribution



Control Charts and Quality Loss

Variation & Quality

20

Central Limit Theorem

a critical aspect of the sampling process is that **it shapes the data into a normal distribution**
you can start to see the effects even after a sample size of only 2
the bigger the sample size (n), the tighter and more normal the distribution



Control Charts and Quality Loss

Variation & Quality


21

Control of Variations: Technological Development


statistical representation



continuous on-line measurement



no statistical
representation needed



Control Charts and Quality Loss

Variation & Quality

22

Control Chart Flow Chart

$$C_p = \frac{USL - LSL}{6\sigma_{process}}$$

LSL: lower specification limit
USL: upper specification limit
LCL: lower control limit
UCL: upper control limit

manufacturing engineers do a qualifying run of parts and figure out how to measure critical dimensions

a run chart is plotted to start gaining intuition

manufacturing engineers determine a reasonable sampling rate to start with, and sample means are plotted

statistics determines the control limits

manufacturing engineers determine the rules used to dictate when the process is in control or out of control

the control chart and rules are used to monitor control of a process

design engineers design parts to meet performance/be part of an assembly

design engineers determined the specifications

bad part < LSL ≤ good part ≤ USL < bad part

⚠ specification limits and control limits are determined **independently**

bad process < LCL ≤ good process ≤ UCL < bad process

e.g. Western Electric Rules


capability can be determined and the process can be managed and improved by all

Control Charts and Quality Loss


Variation & Quality

23

Run Chart vs Control Chart



Run Chart specification limits? **ok**
control limits? **no**





Control Chart specification limits? **no**
control limits? **yes**

Control Charts and Quality Loss

Variation & Quality

24

Accuracy vs Precision




Control Charts and Quality Loss


Variation & Quality

25

A Tale of Two Factories



(a)



(b)


Control Charts and Quality Loss

Variation & Quality

26

Quality Loss Function

Often a company will start with standard USL/LSL and then move to QLF even if a product meets the specification, **deviating from the nominal value can lead to a loss in perceived quality**. The QLF attempts to quantify the loss to create more stringent requirements.



$$Loss = k(x - T)^2$$

x: mean value of sample observed
T: nominal or target value of the product
k: proportionality constant

$$k = \frac{C}{(USL - T)^2}$$

C: total cost for units produced with low quality or out of spec (e.g. at the USL)
USL: upper specification limit

k is empirically determined from a collection of data related to various costs associated with a product being perceived as poor quality and producing parts that are out of spec

these costs could include **cost to produce, rework, dispose, refund, repair, recapture customer, brand damage, etc.**

Image Credits

Slide 1:

© Source unknown. All rights reserved. This content is excluded from our Creative Commons license. For more information, see <https://ocw.mit.edu/help/faq-fair-use>.

Slide 21:

- Left and right images © Source unknown. All rights reserved. This content is excluded from our Creative Commons license. For more information, see <https://ocw.mit.edu/help/faq-fair-use>.
- Center image © Make A Gif. All rights reserved. This content is excluded from our Creative Commons license. For more information, see <https://ocw.mit.edu/help/faq-fair-use>.

MIT OpenCourseWare
<https://ocw.mit.edu>

2.008 Design and Manufacturing II
Spring 2025

For information about citing these materials or our Terms of Use, visit: <https://ocw.mit.edu/terms>.